



STELLAR MODEL ST9S - ASSEMBLY INSTRUCTIONS


Use the following instructions to assemble the Model - ST9S.

Tools Required: Screwdriver, Phillips-Head Screwdriver, Allen Wrench.

1. Remove 2 Allen Bolts from Support Post, connect the 2-pin connector from the support post to the base connector, install the Post in the base and secure with the 2 Allen Bolts.

2. Remove the 2 Phillips head screws from the top of the Support Post, connect the 2-pin connectors, install the Lighthouse Support Tube and secure with the 2 Phillips head screws.

3. Remove the 2 Phillips head screws from the Lighthouse Support Tube, install the Lighthouse on the Support Tube and secure with the 2 Phillips head screws.



EQUIPMENT LABELS AND SPECIFICATIONS



ATTENTION, CONSULT MANUAL FOR FURTHER INSTRUCTIONS.
INDICATES SPECIAL USER ATTENTION.



AC VOLTAGE

FUSE TYPE 1.75 AMP, FAST ACTING (FA)



CLASS I DEFIBRILLATION PROOF, TYPE B EQUIPMENT- IPX4 RATED.
INTERNALLY POWERED EQUIPMENT

FOR DRY LOCATIONS
UNIT TO BE USED ONLY IN SPECIFIED ENVIRONMENTAL CONDITIONS
TEMPERATURE: 15 - 30 C (60 - 85 F)
HUMIDITY: 30% - 60% RELATIVE HUMIDITY, NON CONDENSING

ENTELE CERTIFIED

TO UL2601-1

CAN/CSA601.1, IEC 60601-2-46

US

C

